



Coding plug (R 29) Remove (54—577)
Ohmmeter Connect (refer to table)
Resistance values Check (refer to table), replace coding plug (R 29) if values are deviating.

- a Production date
- b Part number
- c Designation of jack

Test table — resistance values

Part number	Connection ohmmeter on jack designation						
	A—D	B—E	D—C	D—H	E—D	E—F	E—G
005 545 07 32	∞	1470—1530 k Ω	0.01—15 Ω	3.21—3.27 k Ω	∞	26.2—27.2 k Ω	501—521 k Ω
005 545 08 32	∞	1470—1530 k Ω	0.01—15 Ω	1.18—2.02 k Ω	∞	25.2—27.2 k Ω	501—521 k Ω

Conventional tool

Multimeter	SUN	DMM—5
------------	-----	-------